General Environmental Incident Summary

Incident: 4159 Date/Time Notice: 7/6/2016 1340 DEM Incident No:

Responsible Party: Keith Boehm

Date Incident:7/5/2016Time Incident:Duration:County:MortonTwp: 139Rng: 82Sec: 15Qtr:Lat: 46.85731Long: -101.01010Method: Address matching

Location Description: Freeway 147, 3825 Business Loop I 94

Submitted By: Lyle Wood Affiliation: Manager

Address: 3825 Business Loop I 94

City: Mandan State: ND Zip: 58554

Received By:

Contact Person: Keith Boehm

2752 34th St

Mandan, ND 58554

Distance Nearest Occupied Building: 150 Feet Release Contained: Yes

Type of Incident: Pipeline Leak

Description of Released Contaminant: premium gasoline

Volume Spilled: Ag Related: No EPA Extremely Hazardous Substance: No Reported to NRC: No

Cause of Incident:

ground settled and broke pipe

Risk Evaluation:

none

of Fatalities: 0 # of Injuries: 0 Affected Medium: 04 - water and soil

Potential Environmental Impacts:

ground water

Action Taken or Planned:

Tank was shutoff and a sump is to be installed.

Wastes Disposal Location: we are planning on building a clay lined dyke and evaporating it.

Agencies Involved:

Friday, July 15, 2016 Page 1 of 2

Date: 7/6/2016 Status: Reviewed - Assigned to NDDoH Division Author: Suess, Bill

Updated Volume:

Notes:

Division of Waste Management, Underground Storage Tank Program has already been on site.

Friday, July 15, 2016 Page 2 of 2